

# Any Spark Can Cause A Wildfire

Use **CAUTION** When Welding and Grinding.

- 
- Keep area clear of vegetation.
  - Have a spotter watch for sparks.
  - Keep water and a fire extinguisher nearby.
  - Wet down work area.
  - Avoid welding during Red Flag conditions or on windy days.

For more information please visit:  
<http://tfsweb.tamu.edu>

Texas A&M Forest Service is an Equal Opportunity/Affirmative Action/  
Veterans/Disability Employer committed to excellence through diversity.



**TEXAS A&M**  
FOREST SERVICE